



Agilent 7010B and 7000D Triple Quadrupole GC/MS Supplies

Agilent supplies for Agilent instruments

Agilent Technologies is committed to optimizing your laboratory's productivity, so we have produced this list of the most commonly ordered supplies and parts for the 7010B and 7000D Triple Quadrupole GC/MS. Keep this list handy so you can quickly find the supplies you need and minimize instrument downtime.

| Foreline pump supplies | Part No. |
|---------------------------------|-------------|
| Foreitte puttip supplies | Part NO. |
| Foreline pump oil, P3, 1 qt | 6040-0834 |
| Rough pump inlet flange | 0905-1463 |
| Oil drain kit for mist filter | 3162-1057 |
| Pump oil drip pan | G1946-00034 |
| Oil mist filter for RV5 pump | G6600-80043 |
| Quiet cover for RV series pumps | G3199C |

| Gas Clean filters | Part No. |
|--|----------|
| Gas Clean purifier, carrier gas | CP17973 |
| Gas Clean purifier kit (includes one connecting unit 1/8 in and two GC/MS filters) | CP17976 |
| Gas Clean purifier kit (includes one connecting unit 1/4 in and two GC/MS filters | CP17977 |
| Gas Clean purifier installation kit | CP17978 |

| Gas filters | Part No. |
|---|-----------|
| Chemical ionization gas purifier | 5190-9071 |
| Big universal trap, 1/8 in fittings, helium (Ar/Me) | RMSH-2 |
| Big universal trap, 1/8 in fittings, nitrogen | RMSN-2 |
| Big universal trap, 1/8 in fitting, hydrogen | RMSHY-2 |
| Mounting clip | UMC-2 |

| Maintenance supplies | Part No. |
|--|-------------|
| Abrasive sheets | 5061-5896 |
| Abrasive powder, aluminum oxide | 393706201 |
| Cloths, lint-free, 23 x 23 cm, 100% cotton, 15/pk | 05980-60051 |
| Cloths, lint-free, 23 x 23 cm, 100% cotton, 300/pk | 9310-4828 |
| Cotton swabs | 5080-5400 |
| Nylon gloves, lint-free, large | 8650-0030 |
| Nylon gloves, lint-free, small | 8650-0029 |
| High vacuum grease, 25 g | 6040-0289 |
| Electron multiplier | G7002-80103 |
| 4 Turn El filament | G7005-60061 |
| CI filament – 2/pk | G7005-60072 |
| Filament assembly for 7010B | G7002-60001 |
| Micro-lon Gauge E with flange | G1960-80303 |
| Replacement glass bulb for PFTBA and PFDTD test sample | G3170-80002 |
| Ferrules and connectors | Part No. |
| Self Tightening column put | 5100-6104 |

| Ferrules and connectors | Part No. |
|---|-----------|
| Self Tightening column nut | 5190-6194 |
| Self Tightening column nut, MS | 5190-5233 |
| Ferrule, 0.4 mm id, 15% graphite/85%Vespel, 0.1 to 0.25 mm column | 5181-3323 |
| Ferrule, 0.5 mm id, 15% graphite/85%Vespel, 0.32 mm column | 5062-3514 |
| | |







Agilent supplies—to help you get the results you need

For greater confidence in your chromatography results, you can optimize your total system with quality Agilent columns and supplies. Our wide range of columns, supplies, kits, and accessories is designed, manufactured, and tested to rigorous Agilent specifications, under a quality system registered to ISO 9001. Why risk compromising your analytical results with anything less than genuine Agilent supplies?

When choosing your columns, Agilent J&W GC columns offer the lowest bleed levels, the best inertness for acids/bases/mixed functional compounds, and the tightest column-to-column reproducibility.

For Agilent's complete listing of columns and supplies, visit www.agilent.com/chem/supplies